

# CORNER RECORD

Document Number


Book 26 Pg 21  
CR 2955

City of LIVERMORE

County of ALAMEDA

, California

Brief Legal Description ISABEL AVENUE NORTH OF VALLECITOS ROAD



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☐  
Rancho ☐ Other ☒  
Date of Survey 05/22/06

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NAVD88 ☐  
Meas. Units: Metric ☐ Imperial ☐

Corner -

Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND BRASS DISK MONUMENT IN MONUMENT WELL ON ISABEL AVENUE,

APPROXIMATELY 330' NORTH OF VALLECITOS ROAD. THE MONUMENT WAS TIED OUT  
WITH LOCAL STRADDLERS PRIOR TO CONSTRUCTION. SEE PLOT ON REVERSE.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SET LOCAL STRADDLERS, AS SHOWN, WITH TAG, STAMPED LS 6884,  
FOR FOUND MONUMENT AT LOCATION SHOWN ON REVERSE.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on APRIL 18 2007

Signed [Signature] P.L.S or R.C.E. No. LS 6884

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed [Signature] P.L.S or R.C.E. No. 5726

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_





HUB & TACK

NAIL & SHINER

N 0° 10' 05" W  
129.21'

S 45° 02' 54" E  
104.77'

S 45° 02' 54" E  
107.06'

HUB & TACK

- FOUND BRASS  
DISK MONUMENT  
IN MONUMENT WELL
- △ SET LOCAL STRADDLER,  
AS SHOWN, WITH TAG  
STAMPED LS 6884

ISABEL AVENUE

VALLECITOS ROAD

SCALE: 1" = 50'  
APRIL 18, 2007